

FIAT LDV DEMO

02 03 2017

AFTER PHOTOS OF RUSTED VEHICLE

HTW 917 EC

This vehicle has +- 19 000 Km and is used as a demo vehicle. It is evident that this vehicle has been tested off road.

It must be noted that the exhaust will not be cleaned off with dry ice blasting. The other areas that will not be cleaned will be the brake callipers and discs. If these areas are cleaned with dry ice blasting they will have to be treated with wax which, could cause brake failure.

The vehicle was high pressure cleaned to remove mud and dirt. The rusted areas were then cleaned off with Dry Ice blasting before treated with Waxoyl Hardwax underbody protection. The motor was treated with Waxoyl engine protector after been cleaned.



WAXOYL
Cavity Protector

Waxo







EUROLIFT 2T.














 **WAXOYL**
Cavity Protector





































 Cavity Protector



WAX
Cavi



PANEL AIR GU
1360A123









